MPN: MSP421051

Fuser Assembly 127V for BROTHER DCP-L5502DN/5512DN, DCP-L5602DN/5652DN/5662DN, HL-L5102DW/5202DW, HL-L6202DW/6402DW, MFC-L5702DW/5802DW, MFC-L5902DW/5912DW, MFC-L6702DW/6902DW/6912DW

Extend the life of your Printers and Copiers. CoreParts offers a wide range of internal parts for printer and Copier, for all major Printer brands that matches the performance of the originals.

- High Quality
- Tested and certified
- Matching Performance
- Reliable with 12 month Warranty



Specifications

Vendor information	**Brand Name**	CoreParts
	Warranty	1 Year(s)